
In case of 2 x 22µ/16V uni
unexpected 6 x 10µ/16V uni
volume changes, 15 x 10µ/16V pol
please replace 1 x 10µ/25V pol
these 25 caps. 1 x 1µ/50V pol
R.Meurer midisoft.de
22/16v
10/16v
10/25v
1/50v
KORG
KLM-2168
NOP OM-2
KORG
CX-3
R.Meurer
midisoft.de